

Insurable Value / Replacement Cost Appraisal

LOCATED AT:

12467 Country Green Boulevard et al Boynton Beach, FL 33437

FOR:

Country Greens at Westchester Homeowners' Assoc., Inc. 3916 Poinciana Drive S, # 9 Lake Worth, FL 33467

AS OF:

March 4th, 2020

BY:

Paul R Cassidy, Cert Gen RZ3176 All Florida Appraisal Group, Inc. 500 S Cypress Road, # 3 Pompano Beach, FL 33060 954/240-8911 (phone); 954/653-0637 (fax) pcassidy02@aol.com

A

RESTRICTED USE Insurable Value / Replacement Cost APPRAISAL REPORT OF:

60 Buildings Located at:

Country Greens at Westchester Boynton Beach, Florida 33437

Date of Inspection:

March 4th, 2020

File Number: 0320-P13890

FOR:

Country Greens at Westchester Homeowners' Association, Inc.

BY:

Paul R. Cassidy State Certified General REA #RZ3176 Certified Marshall & Swift Estimator # 1055763

ALL FLORIDA APPRAISAL GROUP

500 S Cypress Road, # 3 Pompano Beach, Florida 33060 954/240-8911 (phone); 954/653-0637 (fax) pcassidy02@aol.com Paul R. Cassidy State Certified General R.E. Appraiser #RZ3176 All Florida Appraisal Group 500 S Cypress Road, # 3 Pompano Beach, FL 33060

P (954) 240-8911 F (954) 653-0637 pcassidy02@aol.com

Country Greens at Westchester Homeowners' Association, Inc. c/o Campbell Property Management 3916 Poinciana Drive S, # 9
Lake Worth, FL 33467

March 18th, 2020

Reference/Address: Country Greens at Westchester

12467 Country Greens Boulevard et al

Boynton Beach, Florida 33437

Board of Directors,

In accordance with your request, we have appraised the above referenced residential buildings and common area improvements. The report of that appraisal is attached. The sole objective and purpose of this report is to establish an estimate of insurable value (replacement cost) for insurance purposes as of March 4th, 2020. This appraisal report is intended for sole use by the Client / Name Insured in obtaining adequate hazard insurance.

This report is based on a physical analysis of the site and improvements. The report was developed and the report was prepared in accordance with the Uniform Standards of Professional Appraisal Practice. This report is a real estate consulting service and is not a market value appraisal. The following report was prepared in conformity with Standards 4 and 5 of the Uniform Standards of Professional Appraisal Practice (USPAP). Standard 4 addresses the performance of consulting services by an appraiser. Standard 5 addresses the reporting requirements of consulting services by an appraiser. This report is appropriate for the needs of our client and should not be used for any other purpose or submitted to any other person/party. It is also important that the reader does not confuse the value conclusion reported herein with an estimate of market value

Country Greens at Westchester March 18th, 2020 Page Two

Based upon our analysis, it was concluded that the Estimated Insurable Value / Construction Cost for the buildings as of March 4^{th} , 2020 (building and site improvements only - not including land value) to be:

Hazard Value: \$21,745,419.00

Descrip

[Including Site Improvements - see next page for detail]

Respectfully submitted,

Paul R. Cassidy

State Certified General Real Estate Appraiser # RZ3176

Certified Marshall & Swift Estimator # 105576

SUMMARY OF VALUES

Bldg	Association Name	#	Total RCV	Below Ground	Hazard Value
#	Building Street Address / Identification	Units	(above & below ground)	Exclusions	(including HVAC)
	Country Greens at Westchester Homeowners'				
1	12467 Country Greens Blvd (Clubhouse)	0	\$164,566.00	\$10,572.00	\$153,994.00
2	12076 Country Greens Blvd	1	\$193,333.00	\$15,679.00	\$177,654.00
3	12082 Country Greens Blvd	1	\$193,333.00	\$15,679.00	\$177,654.00
4	12088 Country Greens Blvd	1	\$169,461.00	\$13,991.00	\$155,470.00
5	12094 Country Greens Blvd	1	\$185,597.00	\$14,105.00	\$171,492.00
6	12100 Country Greens Blvd	1	\$193,333.00	\$15,679.00	\$177,654.00
7	12106 Country Greens Blvd	1	\$193,333.00	\$15,679.00	\$177,654.00
8	12112 Country Greens Blvd	1	\$169,461.00	\$13,991.00	\$155,470.00
9	12118 Country Greens Blvd	1	\$193,333.00	\$15,679.00	\$177,654.00
10	12124 Country Greens Blvd	1	\$169,461.00	\$13,991.00	\$155,470.00
11	12130 Country Greens Blvd	1	\$169,461.00	\$13,991.00	\$155,470.00
12	12136 Country Greens Blvd	1	\$193,333.00	\$15,679.00	\$177,654.00
13	12142 Country Greens Blvd	1	\$193,333.00	\$15,679.00	\$177,654.00
14	12148 Country Greens Blvd	1	\$169,461.00	\$13,991.00	\$155,470.00
15	12154 Country Greens Blvd	1	\$169,461.00	\$13,991.00	\$155,470.00
16	12160 Country Greens Blvd	1	\$169,461.00	\$13,991.00	\$155,470.00
17	12166 Country Greens Blvd	1	\$193,333.00	\$15,679.00	\$177,654.00
18	12172 Country Greens Blvd	1	\$185,597.00	\$14,105.00	\$171,492.00
19	12178 Country Greens Blvd	1	\$193,333.00	\$15,679.00	\$177,654.00
20	12184 Country Greens Blvd	1	\$193,333.00	\$15,679.00	\$177,654.00
21	12190 Country Greens Blvd	1	\$169,461.00	\$13,991.00	\$155,470.00
22	12196 Country Greens Blvd	1	\$169,461.00	\$13,991.00	\$155,470.00
23	12202 Country Greens Blvd	1	\$169,461.00	\$13,991.00	\$155,470.00
24	12208 Country Greens Blvd	1	\$185,597.00	\$14,105.00	\$171,492.00
25	12214 Country Greens Blvd	1	\$193,333.00	\$15,679.00	\$177,654.00
26	12220 Country Greens Blvd	1	\$169,461.00	\$13,991.00	\$155,470.00

27	12226 Country Greens Blvd	1	\$169,461.00	\$13,991.00	\$155,470.00
28	12232 Country Greens Blvd	1	\$169,461.00	\$13,991.00	\$155,470.00
29	12238 Country Greens Blvd	1	\$193,333.00	\$15,679.00	\$177,654.00
30	12244 Country Greens Blvd	1	\$169,461.00	\$13,991.00	\$155,470.00
31	12250 Country Greens Blvd	1	\$193,333.00	\$15,679.00	\$177,654.00
32	12256 Country Greens Blvd	1	\$169,461.00	\$13,991.00	\$155,470.00
33	12077 - 12095 Country Greens Blvd	4	\$578,974.00	\$35,998.00	\$542,976.00
34	12101 - 12119 Country Greens Blvd	4	\$572,732.00	\$35,835.00	\$536,897.00
35	12125 - 12137 Country Greens Blvd	3	\$453,209.00	\$30,173.00	\$423,036.00
36	12143 - 12149 Country Greens Blvd	2	\$324,801.00	\$22,534.00	\$302,267.00
37	12155 - 12185 Country Greens Blvd	6	\$840,148.00	\$48,836.00	\$791,312.00
38	12191 - 12221 Country Greens Blvd	6	\$848,331.00	\$49,096.00	\$799,235.00
39	12227 - 12239 Country Greens Blvd	3	\$448,066.00	\$29,855.00	\$418,211.00
40	12245 - 12275 Country Greens Blvd	6	\$853,730.00	\$48,966.00	\$804,764.00
41	12281 - 12299 Country Greens Blvd	4	\$578,974.00	\$35,998.00	\$542,976.00
42	12305 - 12323 Country Greens Blvd	4	\$572,732.00	\$35,835.00	\$536,897.00
43	12329 - 12353 Country Greens Blvd	5	\$724,370.00	\$43,124.00	\$681,246.00
44	12123 - 12135 Forest Greens Drive	4	\$599,252.00	\$35,804.00	\$563,448.00
45	12139 - 12155 Forest Greens Drive	5	\$714,512.00	\$42,568.00	\$671,944.00
46	12159 - 12175 Forest Greens Drive	5	\$713,677.00	\$42,433.00	\$671,244.00
47	12179 - 12191 Forest Greens Drive	4	\$561,967.00	\$36,691.00	\$525,276.00
48	12195 - 12203 Forest Greens Drive	3	\$448,066.00	\$29,855.00	\$418,211.00
49	12207 - 12219 Forest Greens Drive	4	\$601,477.00	\$36,370.00	\$565,107.00
50	12223 - 12231 Forest Greens Drive	3	\$453,209.00	\$30,173.00	\$423,036.00
51	12235 - 12255 Forest Greens Drive	6	\$853,730.00	\$48,966.00	\$804,764.00
52	12259 - 12279 Forest Greens Drive	6	\$840,148.00	\$48,836.00	\$791,312.00
53	12283 - 12299 Forest Greens Drive	5	\$692,026.00	\$44,322.00	\$647,704.00
54	12303 - 12315 Forest Greens Drive	4	\$566,761.00	\$37,451.00	\$529,310.00
55	12319 - 12331 Forest Greens Drive	4	\$601,477.00	\$36,370.00	\$565,107.00
56	12190 - 12206 Forest Greens Drive	5	\$714,512.00	\$42,568.00	\$671,944.00
57	12210 - 12222 Forest Greens Drive	4	\$601,477.00	\$36,370.00	\$565,107.00
58	12226 - 12242 Forest Greens Drive	5	\$714,512.00	\$42,568.00	\$671,944.00
59	12266 - 12270 Forest Greens Drive	2	\$277,535.00	\$22,775.00	\$254,760.00
60	12306 - 12314 Forest Greens Drive	3	\$441,757.00	\$30,420.00	\$411,337.00
	Building Totals	150	\$22,968,763.00	\$1,527,369.00	\$21,441,394.00

Additional Improvements		Cost New		Cost New
Swimming Pool		\$102,315.00		\$102,315.00
Pool Equipment w/ Shelter		\$13,840.00		\$13,840.00
Pool Heater (1)		\$4,675.00		\$4,675.00
Pool Patio Deck		\$33,130.00		\$33,130.00
Pool Patio Fencing / Gates		\$9,945.00		\$9,945.00
Vinyl Fencing @ Equipment Area		\$1,130.00		\$1,130.00
Tennis Court (1)		\$34,650.00		\$34,650.00
Tennis Court Fencing		\$10,400.00		\$10,400.00
Bocce Court (1)		\$2,450.00		\$2,450.00
Shade Canopy @ Bocce Court		\$3,405.00		\$3,405.00
Flag Pole (1)		\$1,250.00		\$1,250.00
Mail Boxes (12), Bulletin Board		\$16,325.00		\$16,325.00
Perimeter/Monument Walls - Fencing		\$56,710.00		\$56,710.00
Pool Patio Lighting (7)		\$13,800.00		\$13,800.00
Total Additional Improvements		\$304,025.00		\$304,025.00
Grand Totals	150	\$23,272,788.00	\$1,527,369.00	\$21,745,419.00
Effective Date: 03/04/2020				

SUMMARY OF SALIENT FACTS

Valuation Date: March 4th, 2020

Appraisal Type: Insurable Value/ Replacement Cost Estimate

Property Rights Fee Simple for Improvements only – Insurable / Replacement Cost

Appraised: (Construction Cost) value

Location / Address: 12467 Country Greens Blvd et al, Boynton Beach, FL 33437

County: Palm Beach

Name Insured: Country Greens at Westchester Homeowners' Association, Inc.

Zoning: RM (Residential Multi-Family)

Year Built: 1987 - 1988

Site Information: An irregular-shaped parcel totaling 1,696,350 +/- square feet and/or

38.94 acres.

Census Tract: The buildings are located in Census Tract 0059.54.

(Source: US Census Bureau)

Flood Data:

The buildings are not located within a flood zone area per the National Flood Insurance Program; Map Number 12099C0960F dated 10/05/2017. The subject is located in Flood Zone "X". See Flood Certificate or Survey for confirmation and which, if different, will supersede the information in this section.

Folio Numbers: 00-42-46-02-04-000-2020 through

00-42-46-02-04-000-4000

Distance to Fire Hydrant: Less than 800 feet

Distance to Tidal Water: 3 89 miles east

Building Improvements:

Country Greens at Westchester consists of 59 attached and detached one-story villa style residential buildings. The buildings have between 1 and 6 individual units each and the complex as a whole has 150 privately owned residences. Each unit includes an entry / rear / side terrace area and the majority of units include a one car parking garage. The buildings frame structures are composed of a combination of reinforced concrete block (CBS) and wood frame wall construction. Exterior finishes are stucco and paint. The buildings foundations are poured, steel reinforced concrete slabs over piles. Finished interior construction includes drywall partitions with steel & wood stud framing. The buildings have pitched, wood truss gable style roofs built up and finished with fiberglass shingles. The plumbing includes connections for a single kitchen and two bathrooms per each unit. The HVAC is provided via individual split system types with only the air handlers and thermostats located within each residence. The units are protected with owner maintained smoke detectors and fire extinguishers.

See attached sketches, floor plans and photograph addendums.

Overall Condition: The buildings have received adequate routine continual maintenance and are considered to be in overall average to good condition.

ISO Construction Class 2 (Joisted Masonry): The buildings were visited and on-site measurements performed and compared to those of layout plans provided, if any, as well as the Palm Beach County tax rolls for accuracy.

Additional Structures & Improvements (as requested by the client):

- 1) Clubhouse Building: Concrete block wall construction. Concrete slab. Pitched wood truss roof finished with fiberglass shingles. 1,070 square feet. ISO Construction Class 2 (Joisted Masonry).
- 2) Swimming Pool & Patio Area: Reinforced concrete in-ground swimming with a textured concrete deck. Chain link and aluminum fencing surrounds the pool patio area. Pool equipment located in fiberglass shelters; pool heater located on slab on ground. Seven approximate 12' single fixture lights on metal poles located on the pool patio area.
- 3) Tennis Court (1): One painted asphalt tennis court located on the west side of the clubhouse building. Approximate 12' chain link fence.
- 4) Bocce Court (1): Standard concrete frame/deck.
- 5) Mail Boxes (12): Metal pedestal and boxes located throughout the community.
- 6) Flag Pole (1): Approximate 18' metal pole.

7) Perimeter Wall / Fencing: Masonry construction with stucco and paint finish. Sections of 6' metal fencing at varying intervals along the masonry wall.

Bldg # / Type, Bldg Street Address, # of Units, Gross Building Area is as follows:

Bldg	Bldg	Building Street	#	Finished Floor	Terrace	Garage	Total Gross
#	Туре	Address / Identification	Units	Area (sqft)	Area (sqft)	Area (sqft)	Area (sqft)
1	Club	12467 Country Greens Blvd (Clubhouse)	0	1,070	0	0	1,070
2	Α	12076 Country Greens Blvd	1	1,422	144	266	1,832
3	Α	12082 Country Greens Blvd	1	1,422	144	266	1,832
4	В	12088 Country Greens Blvd	1	1,218	207	274	1,699
5	С	12094 Country Greens Blvd	1	1,257	80	425	1,762
6	Α	12100 Country Greens Blvd	1	1,422	144	266	1,832
7	Α	12106 Country Greens Blvd	1	1,422	144	266	1,832
8	В	12112 Country Greens Blvd	1	1,218	207	274	1,699
9	Α	12118 Country Greens Blvd	1	1,422	144	266	1,832
10	В	12124 Country Greens Blvd	1	1,218	207	274	1,699
11	В	12130 Country Greens Blvd	1	1,218	207	274	1,699
12	Α	12136 Country Greens Blvd	1	1,422	144	266	1,832
13	Α	12142 Country Greens Blvd	1	1,422	144	266	1,832
14	В	12148 Country Greens Blvd	1	1,218	207	274	1,699
15	В	12154 Country Greens Blvd	1	1,218	207	274	1,699
16	В	12160 Country Greens Blvd	1	1,218	207	274	1,699
17	Α	12166 Country Greens Blvd	1	1,422	144	266	1,832
18	С	12172 Country Greens Blvd	1	1,257	80	425	1,762
19	Α	12178 Country Greens Blvd	1	1,422	144	266	1,832
20	Α	12184 Country Greens Blvd	1	1,422	144	266	1,832
21	В	12190 Country Greens Blvd	1	1,218	207	274	1,699
22	В	12196 Country Greens Blvd	1	1,218	207	274	1,699
23	В	12202 Country Greens Blvd	1	1,218	207	274	1,699
24	С	12208 Country Greens Blvd	1	1,257	80	425	1,762
25	Α	12214 Country Greens Blvd	1	1,422	144	266	1,832
26	В	12220 Country Greens Blvd	1	1,218	207	274	1,699
27	В	12226 Country Greens Blvd	1	1,218	207	274	1,699
28	В	12232 Country Greens Blvd	1	1,218	207	274	1,699
29	Α	12238 Country Greens Blvd	1	1,422	144	266	1,832
30	В	12244 Country Greens Blvd	1	1,218	207	274	1,699
31	Α	12250 Country Greens Blvd	1	1,422	144	266	1,832
32	В	12256 Country Greens Blvd	1	1,218	207	274	1,699
33	0	12077 - 12095 Country Greens Blvd	4	5,041	400	547	5,988
34	Р	12101 - 12119 Country Greens Blvd	4	4,977	408	547	5,932
35	1	12125 - 12137 Country Greens Blvd	3	3,799	296	547	4,642
36	Q	12143 - 12149 Country Greens Blvd	2	2,516	200	547	3,263

37	G	12155 - 12185 Country Greens Blvd	6	7,540	608	1094	9,242
38	R	12191 - 12221 Country Greens Blvd	6	7,660	592	1094	9,346
39	J	12227 - 12239 Country Greens Blvd	3	3,771	304	547	4,622
40	Н	12245 - 12275 Country Greens Blvd	6	7,600	600	1094	9,294
41	0	12281 - 12299 Country Greens Blvd	4	5,041	400	547	5,988
42	Р	12305 - 12323 Country Greens Blvd	4	4,977	408	547	5,932
43	S	12329 - 12353 Country Greens Blvd	5	6,350	496	1094	7,940
44	N	12123 - 12135 Forest Greens Drive	4	4,970	408	1094	6,472
45	М	12139 - 12155 Forest Greens Drive	5	6,290	504	1094	7,888
46	L	12159 - 12175 Forest Greens Drive	5	6,230	512	1094	7,836
47	K	12179 - 12191 Forest Greens Drive	4	5,020	408	547	5,975
48	J	12195 - 12203 Forest Greens Drive	3	3,771	304	547	4,622
49	D	12207 - 12219 Forest Greens Drive	4	5,038	400	1094	6,532
50	ı	12223 - 12231 Forest Greens Drive	3	3,799	296	547	4,642
51	Н	12235 - 12255 Forest Greens Drive	6	7,600	600	1094	9,294
52	G	12259 - 12279 Forest Greens Drive	6	7,540	608	1094	9,242
53	F	12283 - 12299 Forest Greens Drive	5	6,451	488	547	7,486
54	E	12303 - 12315 Forest Greens Drive	4	5,141	392	547	6,080
55	D	12319 - 12331 Forest Greens Drive	4	5,038	400	1094	6,532
56	М	12190 - 12206 Forest Greens Drive	5	6,290	504	1094	7,888
57	D	12210 - 12222 Forest Greens Drive	4	5,038	400	1094	6,532
58	М	12226 - 12242 Forest Greens Drive	5	6,290	504	1094	7,888
59	U	12266 - 12270 Forest Greens Drive	2	2,504	208	0	2,712
60	Т	12306 - 12314 Forest Greens Drive	3	3,888	274	547	4,709
		Totals	150	191,767	17,139	31,270	240,176

VALUATION ANALYSIS

DIRECT SALES COMPARISON APPROACH TO VALUE

Not requested and not considered.

INCOME APPROACH TO VALUE

Not requested and not considered.

COST APPROACH TO VALUE

In the case of valuation for INSURANCE PURPOSES, there is NO IMPUTED DEPRECIATION, as the Improvements IF DESTROYED must be replaced in whole.

DEFINITION OF INSURABLE VALUE:

The following definition is used by the Appraisal Institute and others in the valuation industry.

- 1. The portion of the value of an asset or asset group that is acknowledged or recognized under the provisions of an applicable loss insurance policy.
- 2. Value used by insurance companies as the basis for insurance. Often considered to be replacement or reproduction cost less deterioration of non-insurable items. Sometimes cash value or market value, but often entirely a cost concept.

Cost estimates derived from Marshall & Swift / Boeckh BVS [now CoreLogic parent company] software with the most recent costs updates as of September 2019. Administrative and entrepreneurial profit included in price per square foot estimate.

Porch/Terrace areas for the buildings were included under "Building Additions" and therefore not included in the gross floor area of the BVS reports.

See attached 09/2019 Marshall & Swift / Boeckh BVS report below.

Hazard Value

Policy: Country	Policy: Country Greens 3/					
INSURED	Country Greens at Westchester HOA	Effective Date:	3/04/2020			
	3916 Poinciana Drive S, # 9	Expiration Date:				
	Lake Worth, FL 33467	Cost as of:	09/2019			

BUILDING 1 Clubhouse

12467 Country Greens Blvd Boynton Beach, FL 33437

SECTION 1

SUPERSTRUCTURE

TOTAL RC BUILDING1

Occupancy: 100% Clubhouse/Recreation Building Story Height: 12 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 1

Gross Floor Area: 1,070 sq. ft. Irregular Adjustment: None

Construction Quality: 2 - Average

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		236	
Foundations	6,033	8,662	
Foundation Walls, Interior Foundations, Slab (On Ground		
Exterior	79,489		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	20,281		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	40,360	1,674	
Heating, Cooling, Fire Protection, Plumbing, E	lectrical, Elevators		
Built-ins	2,715		
SUBSTRUCTURE			
SUBTOTAL RC	\$148,878	\$10,572	
ADDITIONS			
Misc. Additional Features:			
Canopy, canvas	5,116		
TOTAL RC SECTION 1	\$153,994	\$10,572	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

Clubhouse

\$153,994

\$10,572

Standard Page 1 BY§-C

Hazard Value

Policy: Country Greens 3/18/2020

BUILDING 2 A Type Building

various - see report

Boynton Beach, FL 33437

SECTION 1

SUPERSTRUCTURE

Occupancy: 84% Row House Story Height: 9 ft.

16% Parking Garage 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 1

Gross Floor Area: 1,688 sq. ft. Irregular Adjustment: None

Construction Quality: 1.8 - Average -

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		338	
Foundations	7,279	11,918	
Foundation Walls, Interior Foundations, Slab On	Ground		
Exterior	81,921		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	26,214		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	49,252	3,423	
Heating, Cooling, Fire Protection, Plumbing, Elec	trical, Elevators		
Built-ins	10,014		
SUBSTRUCTURE			
SUBTOTAL RC	\$174,679	\$15,679	
ADDITIONS			
Misc. Additional Features:			
Porch	2,975		
TOTAL RC SECTION 1	\$177,654	\$15,679	
TOTAL RC BUILDING2 A Type Building	\$177,654	\$15,679	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

Hazard Value

Policy: Country Greens 3/18/2020

BUILDING 3 B Type Building

various - see report

Boynton Beach, FL 33437

SECTION 1

Standard

SUPERSTRUCTURE

Occupancy: 81% Row House Story Height: 9 ft.

19% Parking Garage 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 1

Gross Floor Area: 1,492 sq. ft. Irregular Adjustment: None

Construction Quality: 1.8 - Average -

SUMMARY OF COSTS	Reconstruction	Exclusion
SUPERSTRUCTURE		
Site Preparation		298
Foundations	6,204	10,773
Foundation Walls, Interior Foundations, Slab On G	Ground	
Exterior	66,643	
Framing, Exterior Wall, Structural Floor, Roof		
Interior	27,271	
Floor Finish, Ceiling Finish, Partitions		
Mechanicals	42,311	2,920
Heating, Cooling, Fire Protection, Plumbing, Electr	ical, Elevators	
Built-ins	8,763	
SUBSTRUCTURE		
SUBTOTAL RC	\$151,193	\$13,991
ADDITIONS		
Misc. Additional Features:		
Porch	4,277	
TOTAL RC SECTION 1	\$155,470	\$13,991
TOTAL RC BUILDING3 B Type Building	\$155,470	\$13,991

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

BYS-C

Hazard Value

Policy: Country Greens 3/18/2020

BUILDING 4 C Type Building

various - see report

Boynton Beach, FL 33437

SECTION 1

Standard

SUPERSTRUCTURE

Occupancy: 75% Row House Story Height: 9 ft.

25% Parking Garage 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 1

Gross Floor Area: 1,682 sq. ft. Irregular Adjustment: None

Construction Quality: 1.8 - Average -

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		336	
Foundations	6,476	10,651	
Foundation Walls, Interior Foundations, Slab On G	round		
Exterior	79,801		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	28,453		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	45,422	3,118	
Heating, Cooling, Fire Protection, Plumbing, Electri	cal, Elevators		
Built-ins	9,679		
SUBSTRUCTURE			
SUBTOTAL RC	\$169,831	\$14,105	
ADDITIONS			
Misc. Additional Features:			
Porch	1,661		
TOTAL RC SECTION 1	\$171,492	\$14,105	
TOTAL RC BUILDING4 C Type Building	\$171,492	\$14,105	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

BY&S-C

Hazard Value

Policy: Country Greens 3/18/2020

BUILDING 5 O Type Building

various - see report

Boynton Beach, FL 33437

SECTION 1

Standard

SUPERSTRUCTURE

Occupancy: 88% Row House Story Height: 9 ft.

12% Parking Garage 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 1

Gross Floor Area: 5,588 sq. ft. Irregular Adjustment: None

Construction Quality: 1.8 - Average -

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		1,119	
Foundations	25,242	23,833	
Foundation Walls, Interior Foundations, Slab On C	Ground		
Exterior	203,395		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	106,151		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	166,314	11,046	
Heating, Cooling, Fire Protection, Plumbing, Elect	rical, Elevators		
Built-ins	33,593		
SUBSTRUCTURE			
SUBTOTAL RC	\$534,695	\$35,998	
ADDITIONS			
Misc. Additional Features:			
Porch	8,281		
TOTAL RC SECTION 1	\$542,976	\$35,998	
TOTAL RC BUILDING5 O Type Building	\$542,976	\$35,998	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

B¥S-C

Hazard Value

Policy: Country Greens 3/18/2020

BUILDING 6 P Type Building

various - see report

Boynton Beach, FL 33437

SECTION 1

Standard

SUPERSTRUCTURE

Occupancy: 88% Row House Story Height: 9 ft.

12% Parking Garage 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 1

Gross Floor Area: 5,524 sq. ft. Irregular Adjustment: None

Construction Quality: 1.8 - Average -

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		1,107	
Foundations	24,953	23,682	
Foundation Walls, Interior Foundations, Slab On G	Ground		
Exterior	198,037		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	104,968		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	167,302	11,046	
Heating, Cooling, Fire Protection, Plumbing, Electr	rical, Elevators		
Built-ins	33,208		
SUBSTRUCTURE			
SUBTOTAL RC	\$528,468	\$35,835	
ADDITIONS			
Misc. Additional Features:			
Porch	8,429		
TOTAL RC SECTION 1	\$536,897	\$35,835	
TOTAL RC BUILDING6 P Type Building	\$536,897	\$35,835	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

BY&S-C

Hazard Value

Policy: Country Greens 3/18/2020

BUILDING 7 I Type Building

various - see report

Boynton Beach, FL 33437

SECTION 1

Standard

SUPERSTRUCTURE

Occupancy: 87% Row House Story Height: 9 ft.

13% Parking Garage 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 1

Gross Floor Area: 4,346 sq. ft. Irregular Adjustment: None

Construction Quality: 1.8 - Average -

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		870	
Foundations	19,409	20,527	
Foundation Walls, Interior Foundations, Slab On Gr	ound		
Exterior	164,808		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	82,171		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	124,494	8,776	
Heating, Cooling, Fire Protection, Plumbing, Electric	cal, Elevators		
Built-ins	26,041		
SUBSTRUCTURE			
SUBTOTAL RC	\$416,923	\$30,173	
ADDITIONS			
Misc. Additional Features:			
Porch	6,113		
TOTAL RC SECTION 1	\$423,036	\$30,173	
TOTAL RC BUILDING7 I Type Building	\$423,036	\$30,173	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

BYS-C

Hazard Value

Policy: Country Greens 3/18/2020

BUILDING 8 Q Type Building

various - see report

Boynton Beach, FL 33437

SECTION 1

Standard

SUPERSTRUCTURE

Occupancy: 82% Row House Story Height: 9 ft.

18% Parking Garage 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 1

Gross Floor Area: 3,063 sq. ft. Irregular Adjustment: None

Construction Quality: 1.8 - Average -

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		613	
Foundations	12,893	16,023	
Foundation Walls, Interior Foundations, Slab On G	round		
Exterior	126,513		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	55,218		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	86,459	5,898	
Heating, Cooling, Fire Protection, Plumbing, Electri	cal, Elevators		
Built-ins	18,050		
SUBSTRUCTURE			
SUBTOTAL RC	\$299,132	\$22,534	
ADDITIONS			
Misc. Additional Features:			
Porch	4,135		
TOTAL RC SECTION 1	\$303,267	\$22,534	
TOTAL RC BUILDING8 Q Type Building	\$303,267	\$22,534	_

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

Bys-C

Hazard Value

Policy: Country Greens 3/18/2020

BUILDING 9 G Type Building

various - see report

Boynton Beach, FL 33437

SECTION 1

Standard

SUPERSTRUCTURE

CHIMANA DV OF COCTO

Occupancy: 87% Row House

13% Parking Garage 9 ft.

Decement

Story Height: 9 ft.

Evaluation

Ву҉Ѕ-С

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 1

Gross Floor Area: 8,634 sq. ft. Irregular Adjustment: None

Construction Quality: 1.8 - Average -

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		1,729	
Foundations	38,559	30,060	
Foundation Walls, Interior Foundations, Slab Or	Ground		
Exterior	282,382		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	160,843		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	245,224	17,047	
Heating, Cooling, Fire Protection, Plumbing, Ele	ctrical, Elevators		
Built-ins	51,734		
SUBSTRUCTURE			
SUBTOTAL RC	\$778,742	\$48,836	
ADDITIONS			
Misc. Additional Features:			
Porch	12,570		
TOTAL RC SECTION 1	\$791,312	\$48,836	
TOTAL RC BUILDING9 G Type Building	\$791,312	\$48,836	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

Hazard Value

Policy: Country Greens 3/18/2020

BUILDING 10 R Type Building

various - see report

Boynton Beach, FL 33437

SECTION 1

SUPERSTRUCTURE

TOTAL RC BUILDING10

Standard

Occupancy: 87% Row House Story Height: 9 ft.

13% Parking Garage 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 1

Gross Floor Area: 8,754 sq. ft. Irregular Adjustment: None

Construction Quality: 1.8 - Average -

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		1,753	
Foundations	39,095	30,296	
Foundation Walls, Interior Foundations, Slab O	n Ground		
Exterior	285,540		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	163,025		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	246,895	17,047	
Heating, Cooling, Fire Protection, Plumbing, Ele	ectrical, Elevators		
Built-ins	52,453		
SUBSTRUCTURE			
SUBTOTAL RC	\$787,008	\$49,096	
ADDITIONS			
Misc. Additional Features:			
Porch	12,227		
TOTAL RC SECTION 1	\$799,235	\$49,096	

\$799,235

\$49,096

R Type Building

Hazard Value

Policy: Country Greens 3/18/2020

BUILDING 11

J Type Building

various - see report

Boynton Beach, FL 33437

SECTION 1

SUPERSTRUCTURE

Construction Quality:

SUPERSTRUCTURE

Occupancy: 87% Row House

Story Height: 9 ft.

13% Parking Garage

9 ft.

Construction Type: 100% Joisted Masonry (ISO 2)

Number of Stories:

20,291

Irregular Adjustment:

1 None

Gross Floor Area: 4,318 sq. ft.

SUMMARY OF COSTS Reconstruction Exclusion

Site Preparation 858

Foundations 19,130

Exterior 162,685

1.8 - Average -

Framing, Exterior Wall, Structural Floor, Roof

Foundation Walls, Interior Foundations, Slab On Ground

Interior 80,964

Floor Finish, Ceiling Finish, Partitions

Mechanicals 123,484 8,706

Heating, Cooling, Fire Protection, Plumbing, Electrical, Elevators

Built-ins 25,666

SUBSTRUCTURE

SUBTOTAL RC \$411,929 \$29,855

ADDITIONS

Misc. Additional Features:

Porch 6,282

TOTAL RC SECTION 1 \$418,211 \$29,855

TOTAL RC BUILDING11 J Type Building \$418,211 \$29,855

Hazard Value

Policy: Country Greens 3/18/2020

BUILDING 12 H Type Building

various - see report

Boynton Beach, FL 33437

SECTION 1

SUPERSTRUCTURE

Occupancy: 87% Row House Story Height: 9 ft.

13% Parking Garage 9 ft.

\$804,764

\$48,966

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 1

Gross Floor Area: 8,694 sq. ft. Irregular Adjustment: None

Construction Quality: 1.8 - Average -

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		1,741	
Foundations	38,827	30,178	
Foundation Walls, Interior Foundations, Slab Or	n Ground		
Exterior	283,962		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	161,893		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	255,594	17,047	
Heating, Cooling, Fire Protection, Plumbing, Ele	ectrical, Elevators		
Built-ins	52,093		
SUBSTRUCTURE			
SUBTOTAL RC	\$792,368	\$48,966	
ADDITIONS			
Misc. Additional Features:			
Porch	12,396		
TOTAL RC SECTION 1	\$804,764	\$48,966	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

H Type Building

TOTAL RC BUILDING12

Hazard Value

Policy: Country Greens 3/18/2020

BUILDING 13 S Type Building

various - see report

Boynton Beach, FL 33437

SECTION 1

SUPERSTRUCTURE

Occupancy: 85% Row House Story Height: 9 ft.

15% Parking Garage 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 1

Gross Floor Area: 7,444 sq. ft. Irregular Adjustment: None

Construction Quality: 1.8 - Average -

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		1,490	
Foundations	32,480	27,047	
Foundation Walls, Interior Foundations, Slab On	Ground		
Exterior	251,710		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	135,989		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	206,509	14,587	
Heating, Cooling, Fire Protection, Plumbing, Elec	ctrical, Elevators		
Built-ins	44,309		
SUBSTRUCTURE			
SUBTOTAL RC	\$670,997	\$43,124	
ADDITIONS			
Misc. Additional Features:			
Porch	10,249		
TOTAL RC SECTION 1	\$681,246	\$43,124	
TOTAL RC BUILDING13 S Type Building	\$681,246	\$43,124	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

Hazard Value

Policy: Country Greens 3/18/2020

BUILDING 14 N Type Building

various - see report

Boynton Beach, FL 33437

SECTION 1

Standard

SUPERSTRUCTURE

Occupancy: 82% Row House Story Height: 9 ft.

18% Parking Garage 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 1

Gross Floor Area: 6,064 sq. ft. Irregular Adjustment: None

Construction Quality: 1.8 - Average -

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		1,213	
Foundations	25,525	23,305	
Foundation Walls, Interior Foundations, Slab Or	Ground		
Exterior	214,756		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	107,531		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	171,473	11,286	
Heating, Cooling, Fire Protection, Plumbing, Ele	ctrical, Elevators		
Built-ins	35,734		
SUBSTRUCTURE			
SUBTOTAL RC	\$555,019	\$35,804	
ADDITIONS			
Misc. Additional Features:			
Porch	8,429		
TOTAL RC SECTION 1	\$563,448	\$35,804	
TOTAL RC BUILDING14 N Type Building	\$563,448	\$35,804	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

Hazard Value

Policy: Country Greens 3/18/2020

BUILDING 15 M Type Building

various - see report

Boynton Beach, FL 33437

SECTION 1

Standard

SUPERSTRUCTURE

Occupancy: 85% Row House Story Height: 9 ft.

15% Parking Garage 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 1

Gross Floor Area: 7,384 sq. ft. Irregular Adjustment: None

Construction Quality: 1.8 - Average -

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		1,478	
Foundations	32,218	26,924	
Foundation Walls, Interior Foundations, Slab Or	n Ground		
Exterior	250,084		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	134,938		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	200,335	14,166	
Heating, Cooling, Fire Protection, Plumbing, Ele	ectrical, Elevators		
Built-ins	43,951		
SUBSTRUCTURE			
SUBTOTAL RC	\$661,526	\$42,568	
ADDITIONS			
Misc. Additional Features:			
Porch	10,418		
TOTAL RC SECTION 1	\$671,944	\$42,568	

TOTAL RC BUILDING15	M Type Building	\$671,944	\$42,568	

ByS-C

Hazard Value

Policy: Country Greens 3/18/2020

BUILDING 16 L Type Building

various - see report

Boynton Beach, FL 33437

SECTION 1

Standard

SUPERSTRUCTURE

Occupancy: 85% Row House Story Height: 9 ft.

15% Parking Garage 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 1

Gross Floor Area: 7,324 sq. ft. Irregular Adjustment: None

Construction Quality: 1.8 - Average -

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		1,466	
Foundations	31,956	26,801	
Foundation Walls, Interior Foundations, Slab On	Ground		
Exterior	248,457		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	133,830		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	202,827	14,166	
Heating, Cooling, Fire Protection, Plumbing, Elec	ctrical, Elevators		
Built-ins	43,594		
SUBSTRUCTURE			
SUBTOTAL RC	\$660,663	\$42,433	
ADDITIONS			
Misc. Additional Features:			
Porch	10,581		
TOTAL RC SECTION 1	\$671,244	\$42,433	
TOTAL RC BUILDING16 L Type Building	\$671,244	\$42,433	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

Bys-C

Hazard Value

Policy: Country Greens 3/18/2020

BUILDING 17 K Type Building

various - see report

Boynton Beach, FL 33437

SECTION 1

Standard

SUPERSTRUCTURE

Construction Type: Gross Floor Area:

CLIMANA DV OF COCTO

Occupancy: 90% Row House

Story Height: 9 ft. 9 ft.

Bys-C

10% Parking Garage 100% Joisted Masonry (ISO 2)

Number of Stories:

1

Irregular Adjustment: None

Evaluation

Decement

Construction Quality: 1.8 - Average -

5,567 sq. ft.

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		1,116	
Foundations	25,719	24,304	
Foundation Walls, Interior Foundations, Slab O	n Ground		
Exterior	177,859		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	108,034		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	171,547	11,271	
Heating, Cooling, Fire Protection, Plumbing, El	ectrical, Elevators		
Built-ins	33,687		
SUBSTRUCTURE			
SUBTOTAL RC	\$516,847	\$36,691	
ADDITIONS			
Misc. Additional Features:			
Porch	8,429		
TOTAL RC SECTION 1	\$525,276	\$36,691	
TOTAL RC BUILDING17 K Type Building	\$525,276	\$36,691	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

Hazard Value

Policy: Country Greens 3/18/2020

BUILDING 18 D Type Building

various - see report

Boynton Beach, FL 33437

SECTION 1

SUPERSTRUCTURE

Occupancy: 82% Row House Story Height: 9 ft.

18% Parking Garage 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 1

Gross Floor Area: 6,132 sq. ft. Irregular Adjustment: None

Construction Quality: 1.8 - Average -

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		1,227	
Foundations	25,811	23,450	
Foundation Walls, Interior Foundations, Slab On G	round		
Exterior	216,671		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	108,662		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	169,561	11,693	
Heating, Cooling, Fire Protection, Plumbing, Electr	ical, Elevators		
Built-ins	36,135		
SUBSTRUCTURE			
SUBTOTAL RC	\$556,842	\$36,370	
ADDITIONS			
Misc. Additional Features:			
Porch	8,265		
TOTAL RC SECTION 1	\$565,107	\$36,370	
TOTAL RC BUILDING18 D Type Building	\$565,107	\$36,370	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

Hazard Value

Policy: Country Greens 3/18/2020

BUILDING 19 F Type Building

various - see report

Boynton Beach, FL 33437

SECTION 1

Standard

SUPERSTRUCTURE

Occupancy: 92% Row House Story Height: 9 ft.

8% Parking Garage 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 1

Gross Floor Area: 6,998 sq. ft. Irregular Adjustment: None

Construction Quality: 1.8 - Average -

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		1,403	
Foundations	33,049	28,184	
Foundation Walls, Interior Foundations, Slab On O	Ground		
Exterior	210,181		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	138,042		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	213,723	14,735	
Heating, Cooling, Fire Protection, Plumbing, Elect	rical, Elevators		
Built-ins	42,624		
SUBSTRUCTURE			
SUBTOTAL RC	\$637,619	\$44,322	
ADDITIONS			
Misc. Additional Features:			
Porch	10,085		
TOTAL RC SECTION 1	\$647,704	\$44,322	
TOTAL RC BUILDING19 F Type Building	\$647,704	\$44,322	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

ВУЯ-С

Hazard Value

Policy: Country Greens 3/18/2020

BUILDING 20 E Type Building

various - see report

Boynton Beach, FL 33437

SECTION 1

SUPERSTRUCTURE

Occupancy: 90% Row House Story Height: 9 ft.

10% Parking Garage 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 1

Gross Floor Area: 5,688 sq. ft. Irregular Adjustment: None

Construction Quality: 1.8 - Average -

SUMMARY OF COSTS	Reconstruction	Exclusion	
SUPERSTRUCTURE			
Site Preparation		1,140	
Foundations	26,278	24,594	
Foundation Walls, Interior Foundations, Slab Or	Ground		
Exterior	180,732		
Framing, Exterior Wall, Structural Floor, Roof			
Interior	110,410		
Floor Finish, Ceiling Finish, Partitions			
Mechanicals	169,368	11,717	
Heating, Cooling, Fire Protection, Plumbing, Ele	ctrical, Elevators		
Built-ins	34,420		
SUBSTRUCTURE			
SUBTOTAL RC	\$521,208	\$37,451	
ADDITIONS			
Misc. Additional Features:			
Porch	8,102		
TOTAL RC SECTION 1	\$529,310	\$37,451	
TOTAL RC BUILDING20 E Type Building	\$529,310	\$37,451	

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

Hazard Value

Policy: Country Greens 3/18/2020

BUILDING 21 U Type Building

various - see report

Boynton Beach, FL 33437

SECTION 1

Standard

SUPERSTRUCTURE

SUMMARY OF COSTS

Occupancy: 100% Row House Story Height: 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 1

Gross Floor Area: 2,504 sq. ft. Irregular Adjustment: None

Reconstruction

Exclusion

Construction Quality: 1.8 - Average -

TOTAL RC SECTION 1	\$254,760	\$22,775	
Porch	4,304		
Misc. Additional Features:			
ADDITIONS			
SUBTOTAL RC	\$250,456	\$22,775	
SUBSTRUCTURE			
Built-ins	14,917		
Heating, Cooling, Fire Protection, Plumbing, Electrical,			
Mechanicals	79,535	5,672	
Floor Finish, Ceiling Finish, Partitions			
Interior	52,446		
Framing, Exterior Wall, Structural Floor, Roof			
Exterior	91,305		
Foundation Walls, Interior Foundations, Slab On Groun	d		
Foundations	12,253	16,623	
Site Preparation		480	
SUPERSTRUCTURE			

TOTAL RC BUILDING21	U Type Building	\$254,760	\$22,775	

Hazard Value

Policy: Country Greens 3/18/2020

BUILDING 22 T Type Building

various - see report

Boynton Beach, FL 33437

SECTION 1

Standard

SUPERSTRUCTURE

Occupancy: 87% Row House Story Height: 9 ft.

13% Parking Garage 9 ft.

Construction Type: 100% Joisted Masonry (ISO 2) Number of Stories: 1

Gross Floor Area: 4,435 sq. ft. Irregular Adjustment: None

Construction Quality: 1.8 - Average -

SUMMARY OF COSTS	Reconstruction	Exclusion
SUPERSTRUCTURE		
Site Preparation		888
Foundations	19,806	20,756
Foundation Walls, Interior Foundations, Slab On Gr	ound	
Exterior	143,052	
Framing, Exterior Wall, Structural Floor, Roof		
Interior	83,812	
Floor Finish, Ceiling Finish, Partitions		
Mechanicals	132,138	8,776
Heating, Cooling, Fire Protection, Plumbing, Electric	cal, Elevators	
Built-ins	26,574	
SUBSTRUCTURE		
SUBTOTAL RC	\$405,382	\$30,420
ADDITIONS		
Misc. Additional Features:		
Porch	5,955	
TOTAL RC SECTION 1	\$411,337	\$30,420
TOTAL RC BUILDING22 T Type Building	\$411,337	\$30,420

MS/B costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

ВУД-С

Photograph Addendum

Borrower	N/A			
Property Address	12467 Country Green Boulevard et al			
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437
Lender/Client	Country Greens at Westchester Homeo	wners' Assoc Inc.		






representative residential building

representative residential building







representative residential building



representative residential building



representative residential building

Photograph Addendum

Borrower	N/A			
Property Address	12467 Country Green Boulevard et al			
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437
Lender/Client	Country Greens at Westchester Homeo	wners' Assoc Inc.		





representative residential building

distance to fire hydrant < 150'





representative residential building

representative residential building





representative residential building

representative residential building

Photograph Addendum

Borrower	N/A			
Property Address	12467 Country Green Boulevard et al			
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437
Lender/Client	Country Greens at Westchester Homeo	wners' Assoc., Inc.		





clubhouse

pool patio equipment / heater





swimming pool

clubhouse rear







vinyl fencing @ equipment area

Photograph Addendum

Borrower	N/A			
Property Address	12467 Country Green Boulevard et al			
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437
Lender/Client	Country Greens at Westchester Homeo	wners' Assoc Inc.		



site lighting



pool patio lighting



tennis court / fencing



flag pole



clubhouse interior



bocce court

Photograph Addendum

Borrower	N/A					
Property Address	12467 Country Green Boulevard et al					
City	Boynton Beach	County Palm Beach	State	FL	Zip Code	33437
Lender/Client	Country Greens at Westchester Homeo	wners' Assoc Inc				





perimeter walls / fencing



perimeter walls / fencing




clubhouse interior




patio / lighting canopy @ clubhouse

Borrower	N/A				
Property Address	12467 Country Green Boulevard et al				
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westchester Home	owners' Assoc., Inc.			




Representative of Type "A and A1" Building

Borrower	N/A				
Property Address	12467 Country Green Boulevard et al				
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westchester Homeo	wners' Assoc., Inc.			




Representative of Type "B and B1" Building

Borrower	N/A				
Property Address	12467 Country Green Boulevard et al				
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westchester Homeo	wners' Assoc., Inc.			




Representative of Type "C and C1" Building

Borrower	N/A				
Property Address	12467 Country Green Boulevard et al				
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westchester Home	owners' Assoc., Inc.			




Representative of Type "D" Building

Borrower	N/A				
Property Address	12467 Country Green Boulevard et al				
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westchester Home	owners' Assoc., Inc.			




Representative of Type "E" Building

Borrower	N/A				
Property Address	12467 Country Green Boulevard et al				
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westchester Homeo	wners' Assoc., Inc.			




Representative of Type "F" Building

Borrower	N/A				
Property Address	12467 Country Green Boulevard et al				
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westchester Homeo	wners' Assoc., Inc.			




Representative of Type "G" Building

Borrower	N/A				
Property Address	12467 Country Green Boulevard et al				
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westchester Homeo	wners' Assoc., Inc.			




Representative of Type "H" Building

Borrower	N/A				
Property Address	12467 Country Green Boulevard et al				
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westchester Home	owners' Assoc., Inc.			




Representative of Type "I" Building

Borrower	N/A				
Property Address	12467 Country Green Boulevard et al				
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westchester Home	owners' Assoc., Inc.			




Representative of Type "J" Building

Borrower	N/A				
Property Address	12467 Country Green Boule	vard et al			
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westches	ster Homeowners' Assoc., Inc.			




Representative of Type "K" Building

Borrower	N/A				
Property Address	12467 Country Green Boulevard et al				
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westchester Homeo	Country Greens at Westchester Homeowners' Assoc., Inc.			




Representative of Type "L" Building

Borrower	N/A				
Property Address	12467 Country Green Boulevard et al				
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westchester Home	owners' Assoc., Inc.			




Representative of Type "M" Building

Borrower	N/A				
Property Address	12467 Country Green Boulevard et al				
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westchester Homeo	wners' Assoc., Inc.			




Representative of Type "N" Building

Borrower	N/A				
Property Address	12467 Country Green Boulevard et al				
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westchester Homeo	wners' Assoc., Inc.			




Representative of Type "O and O1" Building

Borrower	N/A				
Property Address	12467 Country Green Boulevard et al				
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westchester Homeo	wners' Assoc., Inc.			




Representative of Type "P" Building

Borrower	N/A				
Property Address	12467 Country Green Boulevard et al				
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westchester Home	owners' Assoc., Inc.			




Representative of Type "Q" Building

Borrower	N/A			
Property Address	12467 Country Green Boulevard et al			
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437
Lender/Client	Country Greens at Westchester Homeowners' Assoc., Inc.			




Representative of Type "R" Building

Borrower	N/A				
Property Address	12467 Country Green Boulevard et al				
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westchester Homeo	wners' Assoc., Inc.			




Representative of Type "S" Building

Borrower	N/A				
Property Address	12467 Country Green Boulevard et al				
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westchester Homeo	Country Greens at Westchester Homeowners' Assoc., Inc.			




Representative of Type "T" Building

Borrower	N/A				
Property Address	12467 Country Green Boulevard et al				
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westchester Homeo	wners' Assoc., Inc.			



Representative of Type "U" Building

Borrower	N/A				
Property Address	12467 Country Green Boulevard et al				
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westchester Homeowners' Assoc., Inc.				



Clubhouse


Aerial Map

Borrower	N/A			
Property Address	12467 Country Green Boulevard et al			
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437
Lender/Client	Country Greens at Westchester Homeowners' Assoc., Inc.			



Location Map

Borrower	N/A				
Property Address	12467 Country Green Boulevard et al				
City	Boynton Beach	County Palm Beach	State FL	Zip Code 33437	
Lender/Client	Country Greens at Westchester Homeowners' Assoc., Inc.				



ASSUMPTIONS AND LIMITING CONDITIONS

The value conclusions and the certification within this report are made expressly subject to the following assumptions and limiting conditions in this report, which are incorporated herein by reference.

- 1. No responsibility is accepted for matters legal in nature; titles is presumed to be good and assumed to be held in fee simple. All existing liens and encumbrances, if any, have been disregarded (unless otherwise stipulated within the report) and the property is appraised as though free and clear, under competent ownership and management.
- 2. The legal description and site drawings furnished (if provided) are assumed to be correct.
- 3. The maps and sketches are included to assist the reader (if provided). Unless a survey of the property has been provided, no responsibility, whatsoever, in connection with such matters will be recognized. Accordingly, the appraiser makes the extraordinary assumption that the square footage indicated herein is correct and is utilizing the departure provision in stating the indicated square footage is found to be different from that as indicted in the property tax rolls, the appraiser accepts no responsibility for same.
- 4. It is assumed that the project herein set forth is an allowable use under the zoning, and is further considered its highest and best use.
- 5. The land and soil of the area under the appraisement appears firm and solid. The analyst was not supplied with an engineering survey and under this condition this appraisal does not warrant this condition.
- 6. Existing buildings involved in this appraisal report have been inspected and damage, if any, by termites, dry rot, wet rot, or other infestations have been reported if discovered as a matter of information but no guarantee of the amount or degree of damage is intended.
- 7. In this appraisal of existing improvements, the physical condition of the improvements was based on a cursory visual inspection. No liability is assumed for the soundness of structural members since no engineering tests were made.
- 8. All furnishings and equipment, except those specifically indicated and typically considered as part or real estate, have been disregarded. Only the real estate has been considered.
- 9. Information furnished by others including comparable sales data is believed to be reliable, but the appraiser assumes no responsibility for its accuracy.
- 10. The fees received for preparation of this report were not contingent upon the final value estimate.

ASSUMPTIONS AND LIMITING CONDITIONS (Continued)

- 11. The appraiser is not required to give testimony or attendance in court by reason of this appraisal with reference to the property in question, unless arrangements have been made previously thereto.
- 12. No consideration has been given to labor bonuses, material premiums, and additional costs to conform property replaced to future building codes, ordinances or other legal restrictions.
- 13. Possession of the reports or copies thereof, does not carry with it the right to publications nor may be used for any purpose by any but the applicant, without the written consent of the appraiser and then with the proper qualifications.
- 14. The valuations may not be used in conjunction with any other appraisal. The conclusions are based upon the program of utilization described herein and have not been separated into parts.
- 15. This appraisal has been made in accordance with the rules of professional ethics of the Appraisal Institute Inc.
- 16. Neither all nor any part of the contents of this report shall be conveyed to the public through advertising, public relations, news, sales, or other media, without the written consent and approval of the author, particularly as to the valuation conclusions, the identity of the appraiser or firms with which they are connected or any reference to the Appraisal Institute Inc., and /or the M.A.I. or S.R.A. designations.
- 17. The estimate of Replacement Cost applies only to the date specified in the report. Replacement Cost of Real Estate is affected by many related and unrelated economic conditions, local and national, which might necessarily affect the future market of the subject property. We, therefore, assume no liability for an unforeseen precipitous change in the economy, the project, region, or property.
- 18. Unless otherwise stated in this report, the existence of hazardous substances, including without limitation asbestos, polychlorinated biphenyls, petroleum leakage, agricultural chemicals, urea formaldehyde foam insulation, toxic waste, other contents of environmental conditions, which may or may not be present on the property has not been considered, they were not called to the attention of the Appraiser, not did the appraiser become aware of such during the Appraiser's inspection. The Appraiser has no knowledge of the existence of such materials on or in the property unless otherwise stated. The appraiser, however, is not qualified to test such substances or conditions. The value estimated is predicated on the assumption that there is no such condition on or in the property or in such proximity thereto that it would cause a loss in value. No responsibility is assumed for any such conditions, or for any expertise or engineering knowledge required to discover them. An expert in this field should be retained by the property owner if deemed appropriate.

ASSUMPTIONS AND LIMITING CONDITIONS (Continued)

- 19. No environmental impact study has been ordered or made. The appraised property is assumed to be in compliance with all applicable regulations unless otherwise noted in the report.
- 20. The date of inspection represents the effective date of the Replacement Cost New opinion and is only considered valid for one year from the effective date. Given the recent price fluctuations for building materials (there is currently an over-supply and limited demand for building labor and materials), the client is strongly advised to annually update the replacement cost new estimate to prevent a situation of either "over/under insuring" the structure. It should be noted that the Replacement Cost New opinion does not consider the following: the cost of replacing pilings or foundation; the loss of use during any reconstruction; real estate taxes during construction; financing costs and/or interest on a construction loan.
- 21. The appraiser is valuing the property for a Replacement Cost Estimate for insurance purposes only. This is to replace the existing improvements in the event of total destruction including removal of existing improvements.

22. Natural Disaster Disclaimer:

Recover and reconstruction from widespread natural disasters such as hurricane or flood will create abnormal shortages of labor and materials, which, in turn will cause above average price increases as much as 50-75% above normal costs prior to the event. These increases, while temporary, may last for a year or more before returning to normal market conditions.

The values as reported herein are estimated based on current (normal) market conditions and are considered appropriate for various purposes including insurance coverage. Some or all of the estimated values as reported herein may be inadequate for reconstruction or repair in periods after a widespread natural disaster.

- 23. In the event of a partial loss, the amount of loss may be based upon the individual repair cost, which is usually proportionately higher than the replacement cost new for the entire property as defined and included in this report.
- 24. The component costs utilized in this report are derived solely from the cost data developed by the Marshall & Swift / Boeckh BVS software. As of July 2011 this is the preferred method, and in certain instances (i.e. Citizen Insurance Company), the only acceptable method of valuation. Information, data and opinions presented in this report are believed to be accurate, however, the author of this report accepts no responsibility for the accuracy of data that was developed by third parties. If Citizens Property Insurance Corporation of Florida (Citizens) is the end user of this report, the appraiser has restrictions on the options allowed via the Marshall & Swift BVS program and may not be fully USPAP compliant. The appraiser cites the Jurisdictional Exception Rule as reasoning to conform with said directives. The rule states: "If any part of USPAP is contrary to the law or public policy of any jurisdiction, only that part shall be void and of no force or effect in that jurisdiction".

- 25. It is agreed that the liability of consultants to the client is limited to the amount of fee paid therefore as liquidated damages.
- 26. Acceptance of, and/or use of, this appraisal report constitutes acceptance of the above conditions.